IN THE ABSTRACT

0

At page 13 at line 2, delete the heading as follows: Adaptive Clock Recovery

Please substitute the paragraph beginning on page 13, line 4 (i.e., the first full paragraph on page 13) with the following paragraph:

A method of recovering a clock signal for a TDM output from packets of TDM data which have been transmitted over a packet network, comprises. The method includes providing a packet buffer to store incoming packets after transmission over the packet network, maintaining a packet count which is incremented as packets arrive at the packet buffer, and decremented each time a packet leaves the packet buffer, and sampling the packet count and controlling the clock frequency of the TDM output on the basis of the sampled packet count.

At page 13 at line 13, delete the following paragraph: Refer to Figure 2